State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code 2D2
Other Listings
Review Code Reviewer Date

Page 1 of 1 *Resource name(s) or number (assigned by recorder) 583 Fell St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 583 Fell St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0830-019

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

583 Fell St. is one of two buildings located on a 28' x 120' through lot on the south side of Fell Street, between Laguna and Buchanan Streets. The second property fronts on Hickory Street and is addressed as 482 Hickory Street (see DPR A form 482 Hickory St.). Built ca. 1890, 583 Fell St is a 3-story, wood frame, multiple family property originally designed in the Stick/Eastlake style. The rectangular-plan building, clad in brick and composite wood shingle siding, is capped by a flat roof. The foundation is not visible from the street. The primary façade faces north and is 2 bays wide. The ground floor is clad in brick and features a garage in the left bay. The right bay contains a dogleg, terrazzo staircase with stuccoed parapet walls leading to the main entrance on the first story. The main entrance is set inside a recessed entry porch with arched opening in the right bay of the first story. The building has two entrances fitted with glazed wood doors with transoms. The left bay of the first story has a rectilinear bay window on exposed joist ends with arched, wood, double-hung sash. The second story has an identical bay window to the first story and the right bay contains a single flush window with identical sash. The primary facade terminates in a bracketed cornice. Secondary elevations feature arched, double-hung, wood windows. A secondary entrance is situated on the ground story of an off set rear block exposed on the east side of the building. The building appears to be in good condition, but has been altered since construction.

*P3b. Resource Attributes: (list attributes and codes) HP3. Multiple Family Property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5b. Photo: (view and date)
View from north
10/30/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1900; rev. ca. 1890
SF Assessor; Sanborn Maps

*P7. Owner and Address:
Gary L & Katherine Murphy
7502 Moss Brook Rd
San Antonio, TX

*P8. Recorded by:
Page & Turnbull, Inc.
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
10/30/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☒ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)