State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code 2D
Other Listings
Review Code Reviewer Date

Page 1 of 2 *Resource name(s) or number (assigned by recorder) 360 Lily St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 360 Lily St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0840-036

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

360 Lily Street is located on a roughly L-shaped lot on the north side of Lily Street, between Buchanan and Laguna Streets. Built circa 1910, 360 Lily Street is a two-story, wood frame, single-family residential building designed in an Eclectic Classical Revival style. The rectangular-plan building, clad in shiplap wood siding, sits on a reinforced concrete perimeter foundation and is capped by a flat roof. The primary façade faces Lily Street and is two bays wide. The typical fenestration is composed of double-hung, wood-sash windows. The building is symmetrical around its vertical axis. The ground floor features pairs of two-over-two, double-hung, arched, wood-sash windows with decorative surround and pediment hood. Above, on the second floor are two semi-hexagonal bay windows with projecting box cornices, spandrel panels, and molded surrounds. The primary façade terminates a false-front parapet, detailed with a flat-front panel frieze, brackets with brackets extension, panel molding, and a projecting cornice with a triangular pediment. The main entrance appears on the east façade, which is distinguished by a six-light glazed wood-panel door with flanking sidelights, and paired and individual double-hung wood-sash windows. The building appears to be in good condition.

*P3b. Resource Attributes: (list attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5a. Photo



P5b. Photo: (view and date)
View of south façade
10/27/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1900; rev. ca. 1910
SF Assessor; Sanborn Maps

*P7. Owner and Address:
Gabriela Ramos
1850 Union St #4 Pmb #1337
San Francisco, CA 94123

*P8. Recorded by:
Page & Turnbull, Inc. (CM)
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
10/27/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)

P5a. Photo (cont'd)

Detail of entrance, east façade.



East façade