State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code
Other Listings
Review Code Reviewer Date

Page 1 of 2 *Resource name(s) or number (assigned by recorder) 119 Haight St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 119 Haight St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0856-021

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

119 Haight Street is located on a 37.5' x 137.5' lot on the south side of Haight Street, between Octavia and Laguna Streets. Built in 1910, 119 Haight Street is a 4-story, wood frame, twenty-eight-unit, multiple-family residential apartment building, designed in an Eclectic Mediterranean Revival style. The rectangular-plan building, clad in brick at the base, rough texture stucco on the upper floors, and horizontal drop wood siding on the secondary façades, sits on a reinforced concrete perimeter foundation and is capped by a flat roof. The primary façade faces north and is four bays wide. At the rasied basement are two single-light awning windows, which appear to be covered up. Between the raised basement and first floors is a watertable running the length of the façade. The first floor features paired eight-over-one, double-hung, wood-sash windows with continuous molded sills in the left and right bays, and a recessed entry porch in the center bay. This entry porch is demarcated by paired columns and a shallow arched opening, along with two square shaped motifs. The entry porch contains a flight of terrazzo stairs and two modern glass doors with molded surrounds and sidelights. The first floor is capped by a projecting cornice with elongated brackets. The upper two floors are characterized by semi-hexagonal bay windows in the left and right bays, and two single windows with flat window hoods in the center bays. (See Continuation Sheet)

*P3b. Resource Attributes: (list attributes and codes) HP3. Multiple family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5a. Photo

P5b. Photo: (view and date)
View from north
9/15/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1910
SF Assessors Office

*P7. Owner and Address:
Charles M Wallis Revoc Liv
% Fisher
452 Douglass St
San Francisco, CA 94114

*P8. Recorded by:
Page & Turnbull, Inc. (CM)
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
9/15/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)

***P3a. Description: (cont'd)**
The bay windows are characterized by sculpted garlands, continuous sills, cornices with brackets, and terracotta tile hipped pent roofs. In the center bay of the second and third floors is a metal first escape. All fenestration on this façade, unless otherwise noted, consists of eight-over-one, double-hung, wood-sash windows with molded surrounds. The primary facade terminates in a tall parapet wall with central and corner piers, and two ornate hipped pent roofs over the projecting bay windows of the first and fourth building bays with ornamental modillions and terracotta tile. The building appears to be in good condition, however the façade's stucco appears to be discolored.

P5a. Photo (cont'd)

Detail of upper floor window.

Detail of cornice.