State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code
Other Listings
Review Code Reviewer Date

Page 1 of 1 *Resource name(s) or number (assigned by recorder) 577 Fell St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 577 Fell St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0830-020

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

577 Fell St. is located on a 25' x 60' lot on the south side of Fell Street, between Laguna and Buchanan Streets. Built ca. 1890, 577 Fell St is a 2-story, wood frame, multiple family dwelling originally designed in the Stick/Eastlake style. The rectangular-plan building, clad in stucco and drop wood siding, is capped by a flat roof. The foundation is not visible from the street. The primary façade, clad in stucco, faces north and is 2 bays wide. The raised basement story features a single, fixed window in the left bay. Concrete steps with stepped, concrete parapet walls lead to the recessed main entrances in the right bay of the first story. The squared recess opening has a painted keystone. The building has two entrances fitted with divided, glazed wood doors with transoms. The left bay of the first and second stories contains a rectilinear bay window with double-hung, wood sash. The right bay of the second story has a single, double-hung, wood window. The primary facade terminates in a paneled frieze and bracketed cornice. Side elevations are clad in drop wood siding. A single bay of an off-set rear block is exposed on the west elevation of the building and features double-hung, wood windows on both stories with architrave surrounds and centered peaks on the lintel. The building appears to be in good condition, but has been substantially altered since construction.

*P3b. Resource Attributes: (list attributes and codes) HP3. Multiple Family Property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5b. Photo: (view and date)
View from north
10/30/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1900; rev. ca. 1890
SF Assessor; Sanborn Maps

*P7. Owner and Address:
Gary Gonzalez
577 Fell St
San Francisco, CA

*P8. Recorded by:
Page & Turnbull, Inc.
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
10/30/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☒ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)