State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code
Other Listings
Review Code Reviewer Date

Page 1 of 1 *Resource name(s) or number (assigned by recorder) 477 Hickory St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 477 Hickory St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0830-012C

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

477 Hickory Street is located on a 53' x 31' lot on the south side of Hickory Street between Buchanan and Laguna Streets. Built in 1890, 477 Hickory Street is a 2- and 3-story, wood-frame, single-family dwelling originally constructed as two separate buildings. The rectangular-plan building, clad in stucco on the facade and T-111 siding on secondary elevations, sits on a reinforced concrete foundation. The building is composed of a 3-story block with flat roof measuring a single bay wide and an adjacent 2-story block with a parapeted gable roof measuring a single bay wide. The primary façade faces north. The 3-story block features a recessed, modern wooden door with single sidelight on the first story. The upper stories contain a rectilinear bay window with tripartite windows composed of a center fixed sash, side casement sash, and fixed bottom lights. A single casement window with fixed bottom light is set immediately adjacent to the tripartite window and on the sides of the bay window. The 3-story block terminates in a plain roofline. The 2-story massing features a garage on the ground floor and a tripartite window on the second story identical to those on the bay windows. The 2-story block terminates in a stepped parapet wall.

The building appears to be in good condition.

*P3b. Resource Attributes: (list attributes and codes) HP2: Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5b. Photo: (view and date)
View from north
10/30/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1890/1992
SF Assessors Office

*P7. Owner and Address:
Keith R Potter
477 Hickory St
San Francisco, CA 94102

*P8. Recorded by:
Page & Turnbull, Inc.
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
10/30/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☒ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)